Lome y

DMV Lane Technician Observation Report

DMV Technician: Jue Riogio Positio	on: 1 or 2		
Station: With 1 to Date: 8-7-13 Time:		2:03	
Vehicle Make: Toy 814 Model me lin -	Year	1990	
GVWR: Fuel Type: 6 25 Registration N			4518
Auditor: Covert (Circle one)			
	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	1		
2. Was Emissions testing required?	-		
a) Was Emissions testing performed using OBD?			
b) Was Emissions testing performed using Analyzer Probe?	1		
c) Was Emissions testing performed using Paddle(s)?	-		
d) Was Emissions testing performed using Clip?			
3. Was Catalytic Converter inspection required?	-		
a) Was Catalytic Converter inspection performed?		-	
4. Was Fuel Tank pressure testing required?	L		•
a) Was Fuel Tank pressure testing performed?	-		
5. Was Fuel Cap pressure testing required?	-		
a) Was Fuel Cap pressure testing performed?	1		
6. Is this test a Re-check from a prior failure?			
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?			
New Castle and Kent Counties Only			
7. Was Two-Speed Idle testing required?	u		
a) Was Two-Speed Idle testing performed?	V		
Sussex County Only			
8. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?			
Comment:			
1 0 A			
Lane Supervisor Signature: - (a car Sang //			

Revised 04/12/2013